

Coal Tip Name	Godre'r-Graig Higher / Pentwyn No. 3 Levels	Tip Ref Number	L044C	
		Ownership Status	Unknown	
Located In	Godre'r-Graig Higher, Neath-Port Talbot	Tip Category	D	
Inspection Led By		Date of Inspection	16/02/2023	Date of last Inspection
Weather	Overcast – Rain & Fog		Wet	Calm
General Remarks (e.g. access, limitations)	Access to the site was gained via an access track situated just off Graig Road, which leads to Pentwyn Farm. It should be noted that this inspection was conducted without the benefit of a detailed site plan. In certain areas, dense vegetation significantly limited accessibility and visual inspection. Therefore, instability within these areas could exist, but was not detectable at the time of the inspection. The location of the tip on privately owned land also limited the coverage of this inspection.			
Features Causing Concern		Description		
		i.	Poor condition and effectiveness of the shallow, unlined cut-off channel, located to the rear of the tip.	
		ii.	Uncontrolled flows, associated scouring and undercutting.	
Item		Change to Condition (New, Worse, No Change or N/A)	Description	
	Ground Movement			
1	Within body of the tip	No Change	Distortion (curvature) of some trees, situated along the flank. Potentially indicative of shallow moving creep.	
		No Change	Several minor, shallow surface slips situated along the toe, adjacent to the access track. Natural ground material exposed along the slip surfaces, with a thin veneer of overlying spoil material evident.	
2	Above the tip	N/A	Cilmaengwyn Landslide (ID – 3549).	
3	Below the tip	N/A		
	Drainage			
4	Surface drainage (e.g. ditches)	No Change	Vegetation and silt debris partially obstructing the shallow, unlined cut-off channel which runs parallel to the access track, located to the rear of the tip. Areas of choking flows along sections of the channel are evident. The channel is ineffectively capturing some flows, with surface runoff migrating downslope	

			along the access track. Flows conveying off-site, adjacent to the front drives/access tracks of residential houses, situated off the main access track.
5	Sub-surface drainage (e.g. French drains, inclined drains)	N/A	
6	Adits, tunnels & culverts	N/A	
7	Ponds & overflows	N/A	
8	Standing water (e.g. saturated ground)	No Change	Saturated ground conditions spatially associated with areas of seepages.
	Structures		
9	Within body of the tip	N/A	
10	Other	N/A	
	Seepage		
11	Within body of the tip	New No Change No Change	Seepage/flows emanating from an unknown brick structure (), located directly adjacent to the incised channel which skirts the eastern perimeter. Flows conveying towards the incised channel. Multiple seepages situated on the north-eastern section of the tip plateau. Flows appear to be conveying towards the incised channel which skirts the eastern boundary. Several seepages emanating from the toe of the tip, conveying downslope via the access track.
12	Above the tip	N/A	
13	Below the tip	N/A	
	Erosion		
14	Surface erosion	N/A	
15	Physical erosion (e.g. scour, undercutting)	No Change No Change	Scouring along the access track which skirts the toe, induced by the downslope migration of strong, uncontrolled runoff. Incised scouring along the eastern boundary, induced by strong flows associated with the unnamed issue/watercourse.

		No Change	Scoured, undercut sections of the toe, induced by conveying flows associated with seepages and the unnamed issue/watercourse which cascades onto the access track.
Pollution & Contamination			
16	Invasive species	N/A	
17	Fly tipping	N/A	
Land Use			
18	Has the land use change	No Change	Vehicle and machinery situated on the north-eastern section of the tip plateau.
19	Has there been any excavation	N/A	
20	Has there been any material deposited	No Change	Sandstone quarry waste material, likely sourced from the nearby Cwar Pentwyn quarry is deposited on the north-eastern section of the tip plateau.
21	Is there sign of burning	N/A	
22	Security (e.g. fencing, access gates, signage)	No Change	'Private Property Keep Out' signage.

	Name	Date	Signature
Approver		21/2/2023	

Coal Tip Name	Godre'r-Graig Higher / Pentwyn No. 3 Levels	Tip Ref Number	L044C
Date of Inspection	16/02/2023	Tip Category	D
		Inspection led by	



Photo No.	1	Comment	Vegetation and silt debris partially obstructing the shallow, unlined cut-off channel which runs parallel to the access track, located to the rear of the tip. Channel ineffectively capturing some flows (LHS), surface runoff migrating downslope, resulting in scouring of the access track. Some flows being conveyed towards the associated small diameter, cast iron culvert inlet (dashed red outline) as intended.



Photo No.	2	Comment	Vegetation and silt debris partially obstructing the shallow, unlined cut-off channel which runs parallel to the access track, located to the rear of the tip. Channel ineffectively capturing some flows, surface runoff migrating downslope, resulting in scouring of the access track. Private property signage present.

Coal Tip Name	Godre'r-Graig Higher / Pentwyn No. 3 Levels	Tip Ref Number	L044C
		Tip Category	D
Date of Inspection	16/02/2023	Inspection led by	



Photo No.	3	Comment	Multiple seepages situated on the north-eastern section of the tip plateau, associated saturated ground conditions. Sandstone quarry waste material deposited on the plateau (RHS).
------------------	---	----------------	---



Photo No.	4	Comment	Seepages conveying from the north-eastern section of the plateau, towards the incised channel which skirts the eastern boundary.
------------------	---	----------------	--

Coal Tip Name	Godre'r-Graig Higher / Pentwyn No. 3 Levels	Tip Ref Number	L044C
		Tip Category	D
Date of Inspection	16/02/2023	Inspection led by	



Photo No.	5	Comment	Seepage/flows emanating from an unknown brick structure, located directly adjacent to the incised channel which skirts the eastern perimeter.



Photo No.	6	Comment	Strong flows associated with the unnamed issue/watercourse, conveying along the eastern boundary. Seepage/flows (LHS) emanating from an unknown brick structure, conveying towards the incised channel.

Coal Tip Name	Godre'r-Graig Higher / Pentwyn No. 3 Levels	Tip Ref Number	L044C
		Tip Category	D
Date of Inspection	16/02/2023	Inspection led by	



Photo No.	7	Comment	Incised scouring along the eastern boundary, induced by strong flows associated with the unnamed issue/watercourse.



Photo No.	8	Comment	Incised scouring along the eastern boundary, where the flows associated with the unnamed issue/watercourse cascade onto the access track.

Coal Tip Name	Godre'r-Graig Higher / Pentwyn No. 3 Levels	Tip Ref Number	L044C
		Tip Category	D
Date of Inspection	16/02/2023	Inspection led by	



Photo No.	9	Comment	View looking north-west across the densely vegetated tip flank. Scoured, undercut section of the toe, where the unnamed issue/watercourse cascades onto the access track. Associated scouring of the adjacent access track, induced by the downslope migration of uncontrolled flows.



Photo No.	10	Comment	View looking across a minor, shallow surface slip situated along the toe, adjacent to the access track. Natural ground material has been exposed along the slip surface, with a thin veneer of overlying spoil material evident.