

Coal Tip Name	Godre'r Graig higher level and Pentwyn No. 2 and 3 - Tip A		Tip Ref Number	T13187	
Located In	Godre'r Graig, Neath-Port Talbot		Ownership Status	Private	
Inspection Led By		Date of Inspection	09/09/2024	Date of last Inspection	08/11/2023
Weather	Sun		Dry	Calm	
General Remarks (e.g. access, limitations)	<p>Access to the site is gained via Clos Cerrig access track, situated just off Graig Road, which leads to Patagonia Farm.</p> <p>It should be noted that this inspection was conducted without the benefit of a detailed site plan. Dense vegetation significantly limited accessibility and visual inspection; with access on to the tip body no longer possible. Therefore, instability within these areas could exist, but was not detectable at the time of the inspection.</p>				
Features Causing Concern		Description			
		i.	Vegetation significantly limiting accessibility and visual inspection.		
		ii.	Presumed that poor condition/partial obstructions to drainage infrastructure remain.		
		iii.	Flows along the back of the tip, unclear if issues are infiltrating the tip body. Unclear where issues are being conveyed to.		
Item		Change to Condition (New, Worse, No Change or N/A)	Description		
	Ground Movement				
1	Within body of the tip				
2	Above the tip				
3	Below the tip				
	Drainage				
4	Surface drainage (e.g. ditches)	N/A	Dense vegetation preventing access to the previously recorded vegetated cut-off channel, situated to the rear of the plateau.		
		No Change	Vegetation partially obstructing the shallow, unlined ditch present along sections of the southern boundary, adjacent to the access track.		
		N/A	Dense vegetation preventing access to the previously recorded vegetated hand-dug channel, associated with the retro-fitted building.		

5	Sub-surface drainage (e.g. French drains, inclined drains)		
6	Adits, tunnels & culverts	N/A	Dense vegetation preventing access to the previously recorded partially obstructed (by vegetation) outlet of the cast iron pipe, of which is driven into the embankment up-slope of the plateau. It has been previously noted that the pipe has been disconnected from the associated steel box structure and the cast iron culvert inlet, resulting in localised ponding.
		N/A	Dense vegetation preventing access to the previously recorded partially obstructed (by vegetation) cast iron culvert outlet, associated with the unlined cut-off channel, situated to the rear of the plateau.
		No Change	Dense vegetation preventing identification and inspection of the Armco pipe outlet, situated within the shallow unlined ditch, adjacent to the access track.
7	Ponds & overflows		
8	Standing water (e.g. saturated ground)		
	Structures		
9	Within body of the tip	N/A	Dense vegetation preventing access to the previously recorded collapsed adit, situated to the rear of the south-western section of the site. Minor ponding of flows and saturated ground conditions have been previously noted.
		No Change	Historical masonry stone retaining wall, located along sections of the toe, adjacent to the access track. Vegetation obstructing visual inspection.
10	Other		
	Seepage		
11	Within body of the tip	No Change	Seepage conveying towards the Armco pipe, situated within the shallow ditch present along sections of the southern boundary, adjacent to the access track.
12	Above the tip	No Change	Strong flows associated with T62866 Tip (up-slope) conveying downslope towards the north-eastern section of the site.
13	Below the tip	N/A	

	Erosion		
14	Surface erosion	N/A	
15	Physical erosion (e.g. scour, undercutting)	N/A	
Pollution & Contamination			
16	Invasive species	N/A	
17	Fly tipping	N/A	
Land Use			
18	Has the land use change	N/A	Retro-fitted colliery building located to the rear of the plateau. Household material and food being stored within a series of smaller buildings associated with the former colliery.
19	Has there been any excavation	N/A	
20	Has there been any material deposited	N/A	
21	Is there sign of burning	N/A	
22	Security (e.g. fencing, access gates, signage)	N/A	

	Name	Date	Signature
Approver		2/10/2024	

Coal Tip Name	Godre'r Graig higher level and Pentwyn No. 2 and 3 - Tip A	Tip Ref Number	T13187
		Tip Category	D
Date of Inspection	09/09/2024	Inspection led by	



Photo No.	1	Comment	Strong flows associated with T62866 Tip (up-slope) conveying downslope towards the north-eastern section of the site.
------------------	---	----------------	---



Photo No.	2	Comment	Dense vegetation along the access path, preventing access onto the tip body.
------------------	---	----------------	--

Coal Tip Name	Godre'r Graig higher level and Pentwyn No. 2 and 3 - Tip A	Tip Ref Number	T13187
		Tip Category	D
Date of Inspection	09/09/2024	Inspection led by	



Photo No.	3	Comment	Vegetation partially obstructing the shallow, unlined ditch present along the southern boundary, adjacent to the access track.
------------------	---	----------------	--



Photo No.	4	Comment	Seepage conveying towards the Armco pipe, situated within the shallow ditch present along sections of the southern boundary, adjacent to the access track.
------------------	---	----------------	--