0 I T' N	Cwar Pentwyn Quarry /	Tip Ref Number		L044B
Coal Tip Name	Cilmaengwyn	Ownership Status		Private
Located in	Godre'r Graig, Neath-Port Talbot	Tip Category		D
Led by	Undertaken on behalf of Welsh G		Government	
Date	05/09/2023	Date of last Detailed Inspection	13	3/06/2019
Weather	Sunny	Dry		Calm
Comments on access and any limitations	Access to the site was gained via an access track situated just off Graig Road, which leads to Pentwyn Farm.  It should be noted that this inspection was conducted without the benefit of a detailed site plan. Dense vegetation significantly limited accessibility and visual inspection. Therefore, instability within these areas could exist, but was not detectable at the time of the inspection. The location of the tip on privately owned land also limited the coverage of this inspection.			
		S		0101
	Investigate ownership of the sany, have been taken with rehistoric spoil.			Status 2
RAG Status: Capital & Maintenance Works	Investigate activity within Cwar Pentwyn to establish if planning or quarry regulations have been breached.			2
	Consider undertaking a UAV geotechnical assessment to f characteristics of the tip.	3		
General Remarks	This site comprises of a disused spoil tip located tip located downslope and adjacent to Cwar Pentwyn Quarry. Relatively recent quarrying activity appears to have been operated for the extraction of road building material, as evidenced by the spoil mounds and relatively recently re-furbished access track. The densely overgrown nature of the site significantly limited (and in most cases prevented) accessibility and visual inspection of the composition of the spoil material. The eastern extent of the site was completely overgrown and inaccessible. The limited exposures of the spoil accounting for the western extent of the site appeared to comprise of clays, sandstone and shale material; likely being associated with the adjacent Quarry as opposed to coal workings. However, there are three recorded adits (274206-11; 274206-19; 274206-25) located just to the south-west of the site boundary; as well as the closely associated 'Godre'r-Graig Higher / Pentwyn No. 3 Levels' coal tip just downslope (approx. 50 m). Therefore, despite no evidence of spoil material being identified (during this visit) within the given site boundary; the poor accessibility means that the possibility of the presence of spoil material cannot be completely discounted.			
		6: 1		Dete
Author	Name	Signature	05	Date 5/09/2023
Approver				5/9/2023

OBSERV	OBSERVATIONS			
		GEOTE	CHNICAL	
ID	Feature	Location	Comment	
N/A				
	L			
	Recommendati	ons		
		DRA	INAGE	
ID.	F			
N/A	Feature	Location	Comment	
11//				
	Recommendati			
	T	ENGINEERING I	NFRASTRUCTURE	
ID	Feature	Location	Comment	
N/A				
	Recommendati	ons		
		INSTRUMENTATI	ON & MONITORING	
ID	Feature	Location	Comment	
N/A				
	Recommendati	ons		
		LAN	ID USE	
ID	Feature	Location	Comment	
23/L/01	Vegetation Cover	Location	The surfaces of the site are densely vegetated with grass,	
	3		bracken, brambles, gorse and trees.	
23/L/02	Signage		'Private Property Keep Out' signage situated on the	
00/1 /00			access track which leads to Pentwyn Farm.	
23/L/03	Land Use		Relatively recent quarrying activity appeared to have taken place, with machinery and mounds of excavated	
			material present. Sandstone quarry waste material has	
			been deposited on the north-eastern section of 'Godre'r-	
			Graig Higher / Pentwyn No. 3 Levels' coal tip, located just	
23/L/04	Land Use		downslope (approx. 50 m).  Evidence of human activity within the Quarry floor, with	
23/L/04	Land Use		the presence of machinery, a boat and electricity	
			extension cables leading downslope (previously recorded	
			as extending downslope towards the properties named	
			'Glanderi' and 'Darren View').	
			Investigate company of the cite and establish what	
			Investigate ownership of the site and establish what measures, if any, have been taken with regard to placing	
			recent materials over historic spoil materials. Investigate	
	Recommendati	one	activity within Cwar Pentwyn to establish if planning or	
	Recommendati	0113	quarry regulations have been breached. Consider	
			undertaking a UAV LIDAR survey. Consider undertaking a geotechnical assessment to fully ascertain the	
			geotechnical characteristics of the tip.	
		CONTAMINATION / (	GEO-ENVIRONMENTAL	
ID	Feature	Location	Comment	
N/A				
	Recommendati	ons		
1.000mmondulono				

	OTHER			
ID	Feature	Location	Comment	
N/A				
	Recommendations			
Any other remarks		arks		

Coal Tip Name  Cwar Pentwyn Quarry /		Tip Ref Number	L044B
Coal Tip Name  Cwal Fellwyll Quality / Cilmaengwyn	Tip Category	D	
Date of Inspection	05/09/2023	Inspection led by	



Photo No.	1	Comment
Feature ID	N/A	Comment

Adit (274206-025) located just to the south-west of the site boundary; associated with the 'Godre'r-Graig Higher / Pentwyn No. 3 Levels' coal tip.



Photo No.	2		the site. Image conveys
Feature ID	23/L/01	Comment	

View looking down the flank of the densely vegetated, eastern extent of the site. Image conveys associated accessibility issues.

Coal Tip Name Cwar Pentwyn Quarry /		Tip Ref Number	L044B
Coal Tip Name  Cilmaengwyn	Tip Category	D	
Date of Inspection	05/09/2023	Inspection led by	



Photo No.	3	Comment
Feature ID	23/L/01	Comment

View looking towards the densely vegetated western extent of the site and adjacent quarry face.



Photo No.	4	Comment	View looking towards the densely vegetated western extent of the site.
Feature ID	23/L/01	Comment	

Coal Tip Name  Cwar Pentwyn Quarry /		Tip Ref Number	L044B
Coal Tip Name  Cwal Fellwyll Quality / Cilmaengwyn	Tip Category	D	
Date of Inspection	05/09/2023	Inspection led by	



Photo No.	5	Comment
Feature ID	23/L/01	Comment

View looking towards a small exposure of sandstones, shales and clays; situated within the densely vegetated western extent of the site.



Photo No.	6	0	Evidence of human activity within the Quarry floor; abandoned boat.
Feature ID	23/L/04	Comment	

Coal Tip Name	Cwar Pentwyn Quarry / Cilmaengwyn	Tip Ref Number	L044B
		Tip Category	D
Date of Inspection	05/09/2023	Inspection led by	



Photo No.	7	
Feature ID	23/L/04	Comment

Evidence of human activity within the Quarry floor, with the presence of electricity extension cables leading downslope (previously recorded as extending downslope towards the properties named 'Glanderi' and 'Darren View').



Photo No.	8	Comment
Feature ID	23/L/01	Comment

Machinery present on the north-eastern section of 'Godre'r-Graig Higher / Pentwyn No. 3 Levels' coal tip, located just downslope (approx. 50 m).

Coal Tip Name	Cwar Pentwyn Quarry / Cilmaengwyn	Tip Ref Number	L044B
		Tip Category	D
Date of Inspection	05/09/2023	Inspection led by	



Photo No.	9	Comment
Feature ID	23/L/01	Comment

Sandstone quarry waste material deposited on the north-eastern section of 'Godre'r-Graig Higher / Pentwyn No. 3 Levels' coal tip, located just downslope (approx. 50 m).